















Cover photograph

An aerial view of Hong Kong depicting the intense hillside development.

Copyright © 2001 Swets & Zeitlinger B.V., Lisse, The Netherlands

All rights reserved. No part of this publication may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording or otherwise, without the prior written permission of the publisher.

Published by: A.A. Balkema, a member of Swets & Zeitlinger Publishers www.balkema.nl and www.szp.swets.nl

For the complete set of volumes: ISBN 90 5809 256 9

For volume 1: ISBN 90 5809 250 X For volume 2: ISBN 90 5809 251 8 For volume 3: ISBN 90 5809 261 5

Printed in the Netherlands

Geotechnical Engineering, Ho & Li (Eds.) © 2001 Swets & Zeitlinger, Lisse, ISBN 90 5809 251 8

## Table of contents

Foreword	IX
Organization	XI
1 Managing Risk in the Interests of Public Safety	
Risk assessment and safety in geotechnics  M. Ziegler	977
2 Environmental Geotechnics	
Environmental considerations of landfill near a Jinkeng Reservoir in Guangzhou, China A. Ho, J. Lui & Q. Shi	983
Influence of headspace concentration of gasoline-contaminated soils  J. Sugawara & K.T. Law	987
Leaching column tests on three estuarine alluvial soils from South Wales, United Kingdom W.Y. Wan Zuhairi, B.K. Tan & R.N. Yong	991
3 The Value of Geotechnics in Construction	
Lateral resistance behaviour of deep foundations in slopes K.S. Chae, K. Ugai & A. Wakai	997
On the physical and identification properties of a slightly organic deposit <i>P.A.L.F. Coelho &amp; L.J.L. Lemos</i>	1001
Finite element analysis of tapered piles sujected to axial loading M. Ghazavi & M.A. Etaati	1005
Numerical analysis of the influence of soil nails on the stability of construction pits <i>Y.H. Hao &amp; R. Azzam</i>	1009
Design of a groundwater lowering system at hillside J.T. Huang, K.K. Yeung & D.H. Wong	1015
Axial capacity of bored piles and pile groups in cemented desert sands N.F. Ismael	1021

Excavation in soft clay with soil improved by jet grouting K.S. Khoo & X.J. Xie	1025
A basement excavation using tie back, internal horizontal strutting and inclined-struts-and-berm system C.S. Lim, S.M. Tan & L.C. Hiew	1031
Changes in the gas permeability of compacted clay liner (CCL) sample under various compaction conditions  S. Moon, J.Y. Kim, M. Chung & K. Nam	1037
Performance of lime-coated granite aggregates in asphalt mixes R. Muniandy, R.S. Radin Umar, S. Hassim, J. Vasudevan, H. Omar & Z. Md. Yusof	1041
Ground improvement using fly ash S.A. Raza, M.S. Ahmad & M.A. Khan	1045
Deformation behaviour of a retaining wall for a deep basement excavation with semi-top down method S.B. Talha	1049
Analysis of sheet pile deflection for deep braced excavation in soft Bangkok clay W. Teparaksa	1055
Pressuremeter tests for geotechnical site investigation in Singapore K. Winn, C.P. Seh & L. Lewis	1059
Case study on the behaviour of driven steel tubular piles J.B. Wang & L.H. Swann	1063
Auger-injected piles floating above karstic marble C.M. Wong & Y.P. Tse	1067
Construction and design of hand-dug caisson foundation in Malaysia Y.W. Yee, J.K.L. Pan & Y.Y. Guo	1071
4 Theoretical Advances and Scientific Innovations	
Centrifuge tests on the failure mechanism of dykes <i>H.G.B. Allersma &amp; A. Rohe</i>	1077
Secondary compression of clays H.N. Bui, J.C. Small & T. Hull	1081
Direct shear strength of a compacted unsaturated silty soil subjected to high total suction <i>T. Nishimura &amp; K. Komagome</i>	1085
Change of undrained shear strength of very soft clay during consolidation Y. Tanaka, G. Imai & M. Katagiri	1089
Time dependent flow in porous media with variable coefficient of permeability $M.M.$ Toufigh	1093
The evolution of damage around an opening in non-persistent jointed rock mass R.H.C. Wong, E.Y.M. Li, P.C.W. Wong & K.T. Chau	1097

Axi-symmetric solutions for layered and porous viscoelastic media L. Yu & G.J. Chen	1101
Further research about passive soil pressure X.Q. Yang, S.X. He & Z.D. Liu	1105
5 Specialty Session on Slope Engineering	
Stabilization of a failed slope with reinforced soil wall <i>C.S. Chen</i>	1111
Analysis of "creep type" landslide using survey data of surface displacement in landslid J. Gunatilake, Y. Iwao, A. Saito & K. Kawasoe	de area 1115
Stability of a high cut in phyllite for the Kali Gandaki Hydropower Plant in Nepal N. Kapali, D. Pant, W. Riemer & S. Shah	1119
A case study – stabilization work to unstable crib wall in residual granite S.K. Kong	1125
Evaluation of slope stability with discriminant analysis H.J. Liao, Y.C. Lin & R.T. Liao	1131
Monitoring of slope movement during remedial works S Maail, H. Omar & D. Lloyd	1135
WWW database of large landslides in Hong Kong – a resource for research and teach A.W. Malone & S.R. Hencher	ing 1139
Slope evaluation based on geological rating and potential instability H. Omar, M. Daud, B.Mohd Zohadie, A.R. Malik, M.M.N. Megat Johari, R.S. Radin Umar & M. Ratnasamy	1143
Stability analysis of bermed embankment on soft clay T. Ruenkrairergsa & P. Promputthangkoon	1147
Assessment of slope stability during the change of matric suction C.H. Ryu & S.K. Kim	1151
Rehabilitation design of distressed cut slope in weathered rocks with relict structures $K.S.\ Soo\ \&\ T.S.\ Yee$	1155
Modular neural networks for rock slope stability assessment Y. Xia, Q. Xie & B. Sha	1159
Time prediction of landslide by gray system model K. Yin & G. An	, 1163
Author index	1167